



1. SLIDE THE SHAFT HOLDING BRACKET OVER THE ADJUSTMENT ROD OF THE BASE AND TIGHTEN USING THE THREE PRONG KNOB.
2. THIS IS DESIGNED TO ADJUST TO MANY DIFFERENT FERRULE TURNING MACHINES.
3. FASTEN BASE , USING #12 X 1 PAN HEAD SCREWS